

PLAN

(CONDITION WITH SUPPORT ALL AROUND GUIDE FRAME)

FACE OF PILE

## NOTES:

- 1. ALL STEEL ANGLES, PLATES AND CONNECTIONS SHALL BE GALVANIZED.
- 2. ALL WELDING TO BE  $\frac{3}{16}$ " FILLET WELDS ALL AROUND BETWEEN CONNECTED PARTS, UNLESS OTHERWISE NOTED.

